



Technical Bulletin from Smartrise Engineering, Inc.

**Date:** October 15, 2015

**TSB Number:** TSBF-0001

**Route to:** Modernization/Service Manager

**Reference:** Door Operation

**Subject:** Door Open/Close Button Functionality

**Action:** Required

**Equipment:** SRH, Hydraulic Controller & SRA Traction Controller

**Description:** Door Open/Close button logic does not function properly

**Do the following:**

1. Download updated software from link below onto laptop
2. Reprogram controller via USB debug adapter onto machine room, car top, and cop j21 and j22
3. Cycle power to initiate software update.

Job Link:

[http://smartrise.info/Software\\_packages/310\\_Building\\_\(150817-005\).zip](http://smartrise.info/Software_packages/310_Building_(150817-005).zip)

**Job(s) on file:**

150817-005      310 BUILDING

Thank you,  
Rob Horton  
Customer Support Manager  
Smartrise Engineering, Inc.

2601 Fair Oaks Blvd., Sacramento, CA 95864  
(p) 916.457.5129 (f) 916.457.4948  
[www.smartrise.us](http://www.smartrise.us)

Office: 916-457-5129 Ext. 301

Cell: 916-203-1292

[rob@smartrise.us](mailto:rob@smartrise.us)

[www.smartrise.us](http://www.smartrise.us)

2601 Fair Oaks Blvd., Sacramento, CA 95864  
(p) 916.457.5129 (f) 916.457.4948  
[www.smartrise.us](http://www.smartrise.us)