

Date: 8/31/2017

TSB Number: TSB-0002

Route to: Modernization/Service Manager

Reference: CXN board

Subject: CXN failing during acceptance test

Action: Required

Equipment: SRH, Hydraulic Controller, SRA Traction Controller, SRD DC Controller

Description: When shorting the E24 bus for acceptance test the fuse on the incoming 24vdc line activates and is not resettable.

Fix: We have removed the fuse.

Do the following:

1. Replace the existing board with the new one.

Affected job(s) on file: